

Facility has five (5) confinement buildings and 2-stage lagoon that recharges the shallow pits that are pull plug. The Breeding and Gestation building had a fresh water line leak as shown on the north west corner of the building was newly constructed and the water line was not properly installed.